



The fitting of ISOEDGE is simple but **IMPORTANT**.

Omissions and faulty workmanship can lead to REJECTION by the Building Control Body/Robust Details Ltd and SOUND TEST FAILURES necessitating COSTLY REPAIRS.

FOR FURTHER INFORMATION CONTACT THERMAL ECONOMICS
TECHNICAL DEPARTMENT ON 01582 544255